



Product Change Notice

PCN NO: G08-00000035

Issue Date: 18th November, 2021

Product(s) affected:

Model Name	Description
WMP-15C/19C/22C WLP-7F20 series WTP-9E66 cable gland series	Realtek audio codec EOL change new codec for product.

Reasons of Change:

According to Realtek ALC-262 Audio codec EOL. Wincomm change Audio codec to Realtek ALC-888S for above product.

Description of Change:

Item	Before change	After change
Vendor	Realtek	Realtek
Audio codec	ALC-262	ALC-888S
Channel support	4	7.1
System I/O	Speaker out/Microphone in Internal Speaker L/R Internal microphone	Speaker out /Microphone in Internal Speaker L/R Internal microphone
Audio driver	Driver for ALC-262	Driver for ALC-888S
System image	Win 7 Image with ALC-262 driver	Win 7 Image with ALC-888S driver
	Win 10 2019 LTSC Image with ALC-262 driver	Win 10 2021 LTSC Image with ALC-888S driver
System BIOS	BIOS for ALC-262	New BIOS for ALC-888S

Impacts on Quality or Reliability:

QA: None

Customer Impacts and Recommended Actions:

Due to the driver of ALC-262 not support ALC-888S, if customers build their own image, they will need to update audio driver for new System.

Contact information:

sales_support@wincomm.com.tw

Sample Order/Implementation Date:

Ready to delivery date: 1st January ,2022

Model Name	Part NO	Order to
As in product(s) affected list	Consult sales account manager for specific part number	sales_support@wincomm.com.tw

Customer Acknowledgement of Receive: Wincomm requests your acknowledgement of this notice. Please contact your sales manager to grant approval or further information. Wincomm will deem this change notice accepted unless specific accepted conditions are received via an email to your contact window within 30 days from the date of this notice issued.